
## STOCK SILENCER

or



 Disconnect the control cables from the exhaust valve on the actuator side; by removing the original link pipe with the catalytic converter, also the valve connected to the link pipe and the cables are removed.
The valve's servo motor should not be removed or disconnected.

Original gasket

## **ART.8074**

KAWASAKI ZX-6R NINJA / KAWASAKI ZX-6R 636 NINJA

LINK PIPE (\*Pre-silencer delete pipe, original catalyst is maintained) Stainless steel